

Regular cleaning and maintenance for oil finished floor

Maintain with “WOCA Maintenance Oil” or, “ WOCA Maintenance Paste’ in regular intervals.

WOCA Maintenance Paste Natural/White

A gelatinous form of the 'WOCA Maintenance Oil' designed specifically for UV oiled and waxed surfaces. This is used to remedy scratches in the floor, and rejuvenate the UV oiled surface, as needed. Produced in a 400ml tube, coverage is 600 square feet tube.'WOCA Maintenance Paste' can be applied manually or mechanically.

Application

- 1) Clean the floor with 125ml 'Wood Cleaner 'mixed into 5litres of water. Leave the floor to dry for at least 8 hours. The floor must be completely dry.
- 2) Apply the 'Maintenance Paste' onto the white polishing pad or cotton cloth. Use a floor machine to correctly distribute the 'Maintenance Paste' for large areas.
- 3) Ensure the Maintenance Paste is distributed uniformly. Buffing continuously until the wood is saturated and appears silky and matt. Apply more Maintenance Paste if necessary.
- 4) If a very matt finish is required, buff with cotton cloths under a polishing pad. Let the surface rest for 4 hours. Do not expose the floor to water for 48 hours after finishing. Alternatively, you can apply “WOCA Maintenance oil” instead of

the paste.

Floor Cleaning

Clean the floor with 125 ml Wood Cleaner mixed into 5 litres water. Leave the floor to dry for at least 8 hours. The floor must be completely dry. In case of extreme dirt, scrub the floor manually using a pad, or by machine. Wipe clean with a mop or cloth. Always wipe a second time in order that as little water as possible remains on the surface. Repeat cleaning procedure if necessary.

Tip: Always work with two buckets – one with Wood Cleaner mixed with water and one with rinse water

Application

- 1) Leave the floor to dry for at least 8 hours. The floor must be completely dry.
- 2) Shake the container carefully. Apply approx. 100 ml oil per 4 m² with a pad, paint roller or cotton cloth, or use a polishing machine for large surfaces.
- 3) It is important that the Maintenance Oil is carefully polished into the wood. Continue polishing until the wood appears saturated and the surface looks uniform.
- 4) Wipe the floor with clean, dry cotton cloths before proceeding with the next section of floor to be finished. The floor should not appear wet and there should not be any excess oil on the surface after polishing. Continue in sections until the floor has been finished. When polished with polishing machine, the floor will be pre-hardened after approx. 4 hours at 20°C and may cautiously be used. Manually polished floors may be used after 24 hours. The surface is fully hardened after 24 hours. Do not expose the floor to water during the hardening time.

WOCA Spot Remover

'Spot Remover' effectively dissolves grease, blood, coffee, tea etc. It is an aerosol solution used as a "last ditch attempt", and it is usually very successful in restoring the floors appearance and re-establishing its protective layer. 'Spot Remover' is based on soap and developed for indoor use, to remove spots from oiled wood surfaces. It is produced in 250 ml spray cans.

Repair Instructions with 'Spot Remover'

***Note:** Before using 'Spot Remover' it is advisable to use a small amount to test in a non-visible area of the floor ensuring that there will be no undesired reaction.*

- 1) Spray 'Spot Remover' evenly on the stain directly from the canister.

- 2) Leave the 'Spot Remover' to dissolve the stain for 10-20min. Now scrub with a brush until the stain has been dissolved.

- 3) Wipe with cloth wrung out in lukewarm water.

- 4) When the floor is completely dry, apply the original surface finish, e.g. oil, wax or soap to re-establish the protection of the surface.

- 5) Repeat the process if necessary.

Tip: After removal of the spot, UV oiled floors should be treated with 'WOCA Maintenance Paste' and soaped floors with soap. It is always recommended to wipe the area around the spot with 'WOCA Natural Soap' after cleaning.